



PURPOSE OF FLIGHT:

Ferry Flight Weyburn to Saskatoon

NATURE OF ACCIDENT:

Battery failed, a/c landed wheels retracted. Pilot failed to take emergency action to lower wheels.

TECHNICAL OFFICER'S REPORT:

It would appear the failure of the electrical system was caused by a weak battery which was completely discharged when u/c was retracted.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LUC / PCDUW / UC DL / UDM

CLASSIFICATION:

5. U/C Failure

SECONDARY OR CONTRIBUTORY FACTORS:

32. U/C Drill - in air

ACTION TAKEN:

*Summary of Evidence*