



PURPOSE OF FLIGHT:

Local flying practice.

NATURE OF ACCIDENT:

Engine failure in air, necessitating forced landing.

TECHNICAL OFFICER'S REPORT:

Exhaust rocker box failure caused loss of power.

FB/AOP/ES/VA/D/1

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

17. Forced landing.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine trouble - accident.

ACTION TAKEN:

NIL