

PURPOSE OF FLIGHT: TECHNICAL OFFICER'S REPORT: Practice circuits & aerobatics. NATURE OF ACCIDENT: Obscure pending investigation. It COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: appears that pilot dived into gully FINDINGS: SUMMARY No.24.73 and failed to pull up in time to CAUSE: Loss of control following recovery from dive. avoid striking the crest of northern possible contributory factors: 1. Occupants blacked side. A/C seems to have mushed into out on recovery. 2. High speed stall may have resulground on belly with right wing slightly ted from pullout, causing a/c to flick to right down and apparently exploded on impactand roll to ground. 3. Inexperience of pilot on type RECOMMENDATIONS: Nil CONCLUSIONS OF A.I.B.: Agree. It is considered that Sat. Churcher was not qualified to carry aerobatics on Harvard a/c due to insufficient dual inst. on type. Flight Commander F/O J. Davidson is responsible for LASSIFICATION: this condition. Sgt. Churcher's Log Book shows no dual Flew into Ground aerobatics. Evidence disclosed disobedience on part of Sgt Taylor of a direct order forbidding Sgt. Taylor to fly in Harvard a/c. This shows a "discipline" sit-SECONDARY OR CONTRIBUTORY FACTORS: uation at Unit which should be looked into, whether it ACTION TAKEN: it is an isolated case or general at 47 S.F.T.S. Nil