

ACCIDENT CLASSIFICATION

UNIT **9 B. & G. S.** COM. **3** PLACE **14 mls. east of Stn. aerodrome, at Baie de Sablès** DATE **27-11-44** TIME **1230**
Mont Joli, P.Q., H.O. FILE **1100-18-13**

A/C TYPE **BATTLE** No. **1813** CRASH CAT. **P.Q. "D"** S.E. **X** M.E. **X** DAY **X** NIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
REGIMBAL, J.P.,	Sgt.	R200066	P.	Uninj.	No.	DATE
BERRY, S.C.,	LAC	R292862	AG/UT	Uninj.	N113	27-11
DALPHOND, R.N.,	Cpl.	R289550	AG/UT	Uninj.	D 14 (REVISED)	
					No.	CHECKED
					6	<input checked="" type="checkbox"/>
					6	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS						
Merlin III	9049/34357	Slightly	ON TYPE		TOTAL			
			INST.	NIGHT	DUAL	SOLO		
			43	19	5	265	127	367

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT

4
2
1
7
4
2
1
1
FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
3RD
INJURY
5
N

PURPOSE OF FLIGHT:

Scheduled Gunnery Ex.,

TECHNICAL OFFICER'S REPORT:

Failure of throttle linkage.

NATURE OF ACCIDENT:

Engine failure in the air - no malfunction of engine prior to failure
throttle linkage apparently became disconnected. A/C forced landed, wheels retracted.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

FB/AOP/ES/MC/D/I/UOK/B

CLASSIFICATION:

17. Forced Landing

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine Trouble - Accident.

ACTION TAKEN:

Nil