

ACCIDENT CLASSIFICATION

U-32 S.F.T.S. Brandon, Man.		COM. 2	PLACE M.A.	DATE 14-12-44	TIME 1130	
A/C TYPE CRANE I.		No. 7918	CRASH CAT. "C"	H.Q. FILE 1100-72-18	S.E.	M.E. X
				DAY	NIGHT X	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
					No.	DATE
BEACH R.A.	F/O	J39491	P	Uninj.	No Sig.	D 14 (REVISED)
NORDIN V.H.	LAC	R192797	PP	Uninj.		
					No.	CHECKED
					3	
					4	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Jacobs	P22550/7027 N11	39	43	125	515	236	591
LAMB-1	S22569/8158 N11	13	4	20	9	68	39

ACCIDENT CLASSIFICATION

CATEGORY

TYPE OF UNIT

TYPE OF A/C

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING

TAXIING

LANDING

TAKE-OFF

FLIGHT

STATRY

FATAL

INJURY

500

5

4

3

2

1

7

6

5

4

3

2

1

30

29

28

27

26

25

24

23

22

21

20

19

18

17

16

15

14

13

12

11

10

9

8

7

6

5

4

3

2

1

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

61

62

PURPOSE OF FLIGHT:

General Clear hood seq.

NATURE OF ACCIDENT:

Structural failure on landing.

TECHNICAL OFFICER'S REPORT:

Structural failure. Failure of port rear nacelle truss members at landing gear yoke bearing supports.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LUC/UDM

CLASSIFICATION:

5. U/C Failure.

SECONDARY OR CONTRIBUTORY FACTORS:

35. U/C Defect

ACTION TAKEN:

Nil