

TECHNICAL OFFICER'S REPORT:, PURPOSE OF FLIGHT: Transportation Flight. NATURE OF ACCIDENT: M/C crashed shortly after take-off. COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: FINDINGS: SUMMARY No. 2544 CAUSE: Primarily. Failure of Stbd. engine for and obscure reason. Secondary. An error in flying on the part of G/C V.B. Corbett, the pilot in that after the stbd. engine had failed he did not carry out prescri bed single engine procedure for Boly. a/c. RECOMMENDATIONS: Court recommend that CAP 100 be amended as follows: - Add: "In case of twin engine a/c, single engine procedure for the type of a/c concerned. CONCLUSIONS OF A.I.B.: Agree, but inclined to believe CLASSIFICATION: that primary cause was pilot error arising out of G/() 14. Out of Control. Corbett's inexperience on type. Notel: G/C Corbett h had insufficient time to be 1st pilot on type. Successful forced landing could have been made with SECONDARY OR CONTRIBUTORY FACTORS: comparative safety if appropriate SE procedure had 26. Engine Trouble - Accident ACTION TAKEN: been adopted. He was negligent in failing to carry out prescribed procedure for testing and run up of engines prior to take off. Failed to sign R. C. A. F. L 20 (REVISED) the flight plan, and Maintenance form . c. c. LTD. 20157.44