

CASPIR Aircraft Accident Cards

Serial: 1383

Title: Beechcraft Expeditor Mk. II / 3T serial:1383 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1945-April-23. Beechcraft Expeditor II s/n 1383. This accident involved 2 people. Ernst RW, Waring RC

Keywords: RCAF Beechcraft Expeditor II, 1383, , RCAF STN, Aerodrome Runway 33 SE, 1945-April-23, Ernst, Waring RCAF L20

Created: 1945-04-23

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000565#1383>

PURPOSE OF FLIGHT:

Check type day.

TECHNICAL OFFICER'S REPORT:

LUC/UDM ✓

Failure of the upper drag strut attachment lugs on the slide assembly.

NATURE OF ACCIDENT:

A/6 made normal circuit and approach and landing. Normal landing was made on runways and during landing run, the stbd. wheel collapsed, allowing a/e to swing off runway damaging wing tip and propellers.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

5. U/C Failure.

SECONDARY OR CONTRIBUTORY FACTORS:

35. U/C Defect.

ACTION TAKEN:

Nil