

PURPOSE OF FLIGHT:	TECHNICAL OFFICER'S REPORT: PCL XOV	
Taxiing.		
NATURE OF ACCIDENT:	Nil	ŗ
Tractor, being used to tow block	court of inquiry or investigating officer	'S REPORT:
cement was left parked in centre	of FINDINGS: SUMMARY No.	O KELOKI.
junction of Hangar apron and tax while driver gave taxi instructi	i strip	΄,
Pilot of Canso which had just 1	ons to anded.Pilot	
of Meechcraft, taxiing to take o	ff position.	, 1
failed to maintain proper lookou	t. did not	
see tractor and taxied into it di	uring turn to	3
)right.Co-pilot of Beechcraft was of a c and not in seat at time of	In luselage	
and tractor driver on stbd. side	of a/c was	,
unable to warn pilot of the obst	ruction.	3
9. Collisions.)
)		
		_
))
) <u>SECONDARY OR CONTRIBUTORY FACTO</u>)	PRS:)
) SECONDARY OR CONTRIBUTORY FACTO)	ACTION TAKEN:	.)
) SECONDARY OR CONTRIBUTORY FACTO)		((: