

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT C.F.S, Trenton,	COM. 1	PLACE 10 mls. N.W. of Watertown, N.Y.,	DATE 26-7-45	TIME 10.30
A/C TYPE VENTURA IIA		NO. FD701	CRASH CAT. "A"	H.Q. FILE 1300-FD701
		S.E.	M.E.	DAY
			X	X

TYPE OF A/C

TYPE OF UNIT

CATEGORY

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL
MORTON, J.F., CAN.	F/O	J29163	P.	Slightly	NO. A.273 DATE 27-7
HARVEY, R.G., CAN.	F/O	J87012	2 P.	Slightly	D 14 (REVISED)
					NO. CHECKED
					2

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Double Wasp	42-228/5006 Ser.						
R2800	H2-293/5012 Slightly	145.	225.	17.	11.	305.	451.
		92.	280.	16.	10.	297.	393.

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF W N

COMMAND

MONTH

STAGE OF FLIGHT

7
4
2
1
7
4
2
1
1
FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
INJURY
3rd
8
N

PURPOSE OF FLIGHT:

To get mutual practice in flying instruction.

NATURE OF ACCIDENT:

Aircraft hit tree while flying in restricted visibility and crashed.

TECHNICAL OFFICER'S REPORT:

ILCO/FCL/POL/WVCO

Nil

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

22. Collision Obstr.

SECONDARY OR CONTRIBUTORY FACTORS:

42. Unauthorized Low Flying.

ACTION TAKEN:

Reprimanded.

Summary