

ACCIDENT CLASSIFICATION

UNIT T62 BR Sqdn.		COM. E	PLACE Small Lake situated 1 ml. N.W. of Blue Mountain		DATE 8-8-45	TIME 1530 GMT
A/C TYPE CANSO "A"		NO. 11077	CRASH CAT. "C"	H.Q. FILE 1100-110-77	S.E.	M.E. X
PERSONNEL		RANK	NUMBER	DUTY	INJURIES	
GRAHAM, R.A.,		F/O	J10100	P.	Uninj.	
NALDRETT, D.A.,		F/L	J8413	2P.	Uninj.	
WITTERICK, W.J.,		F/O	J47808	WAG.	Uninj.	
PULLIN, R.C.		P/O	J52874	Nav.	Uninj.	
HILLMAN, A.B.,		P/O	C51631	Eng.	Uninj.	
LARSON, C.J., USAAF		S/Sgt.	36229986	Eng.	Uninj.	
BULLA USAAF		Lieut.		Pass.	Uninj.	
KRUMM USAAF		Lieut.		Pass.	Uninj.	
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS		
				ON TYPE		TOTAL
				DUAL	SOLO	DUAL
				INST.	NIGHT	SOLO
				78.	147.	3.
				90.	98.	15.
				450.	122.	1818.
				355.	115.	1467.
						1582

COMMAND
MONTH
STAGE OF FLIGHT

4
2
1
7
4
2
1
FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STAIRY
FATAL
INJ. 3RD
5

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Flying supplies to American Repair
Crew located at Pond Lake, Nfld.

TECHNICAL OFFICER'S REPORT:

Nil

MA/XM

NATURE OF ACCIDENT:

Hole in Hull caused when mooring rope
broke and aircraft drifted on Rocks.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

10. Bad Ground.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil

R. C. A. F. L 20 (REVISED)
IM-6-45 (4999) K. P. 36374
H. Q. 885-L 20