

ACCIDENT CLASSIFICATION												
UNIT 122 Comp. Sqdr.			COM. W.A.C.			PLACE Airfield, Pt. Hardy			DATE 22-8-45		TIME 1607	
A/C TYPE HUDSON III			NO. BW 642			CRASH CAT. "B"			H.Q. FILE 1300-BE642		COMMAND	
PERSONNEL			RANK	NUMBER	DUTY	INJURIES		SIGNAL		MONTH		
MURRAY, D.G.,			F/O	J85076	P.	Uninj.		NO. A.121	DATE 22-8	FORCED LANDING		
BENNETT, H.,			F/O	J19250	Nav.	Uninj.		D 14 (REVISED)		TAXIING		
STEVENS, L.E.,			P/O	J93492	WOO	Uninj.		NO. 1	CHECKED	LANDING		
GIBBS, T.T.			LAC	R221359	AFM	Uninj.		2		TAKE-OFF		
VARLEY, F.A.,			LAC	R199291	Elect. Std.	Uninj.				FLIGHT		
STEANE, N.E.			LAC	R223752	WIV	Uninj.				STRATRY		
NAFF, L.A.E.,			LAC	R254360	Instr. Mech.	Uninj.				FATAL		
ENGINE Cyclone G205A		ENGINE NUMBER (S) P.4281456/73223 Ser. S.4281460/73227 N11		INST.		NIGHT		HOURS FLOWN BY PILOTS		STAGE OF FLIGHT		
								ON TYPE		TOTAL		
								DUAL	SOLO	DUAL	SOLO	
								8.	42.	174.	791.	
ACCIDENT CLASSIFICATION												

PURPOSE OF FLIGHT:

Ferrying personnel and equipment.

NATURE OF ACCIDENT:

A/C swung after landing. Swing developed into ground loop and port u/c collapsed.

TECHNICAL OFFICER'S REPORT:

LS/PSS/OSS

Pending

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

2. Swung.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Pending

R. C. A. F. L 20 (REVISED)
IM-6-45 (4989) K. P. 36374
H. Q. 885-L 20

C. C. LTD. 33186-44