

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, ANVESTIGATING OFFICER
Flying instruction	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	Commanding Officers Report - D.14
Harvard 2509 ran into 2506 which	COMPOSITION:
was parked.	
	G/C. F.S. McGill.
	RECOMMENDATIONS:
	Pilots have been warned that despite speed of training and the long flying house (80-90 per month
PRIMARY CAUSE: While the instructor	with 7 week course) every possible care must be
was pointing out Control Tower	taken to avoid accidents due to carelessness.
signals to the pupil, he did not	
notice that the a/c (2509) was	
moving slowly. While so engaged	ACTION TAKEN:  (A) Disciplinary (B) Technical (C) Other
the moving a/c struck a parked a/c (2506).	D.14 approved by A.M.O.T. 25-9-40.
a/c (2500).	D.14 approved by A.M.O.T. 23-9-40.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
	RECORDED BY DATE
	CHECKED BY DATE