

DUTY OF WHICH ENGAGED: OR COMMENDING OFFICER TE OC/ROC/PCDE/ET Navigation instruction. Commanding Officer's Report - D. 14 ME/PH/IL/vok NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE: 16-9-240 After carrying out a practice COMPOSITION: forced landing approach, the aircraft stalled and landed G/C F.S. McGill with wheels retracted. RECOMMENDATIONS: A summary of evidence has been taken and forwarded and it is recommended that the pilot be assessed a PRIMARY CAUSE: portion of the cost of repair. Pilot choked the engine when opening the throttle and had insufficient height or speed to close and reopen it. **ACTION TAKEN:** (A) DISCIPLINARY (B) TECHNICAL (C) OTHER D.14 approved by A.M.O.T. 25-10-40 with the following remarks: "Recommendation that the pilot be assessed a portion of the cost of the repair is not concurred with. SECONDARY CAUSE OR CONTRIBUTING FACTORS: RECORDED BY CHECKED BY