

PILOT		OTHERS		AIRFRAME FAILURE				ENGINE FAILURE				
CAUSES OF ACCIDENTS												
UNIT No. I S.F.T.S.		COM. 1		PLACE Camp Borden, Ontario.				DATE 21-12-40		TIME 1645		
Camp Borden, Ont.		1		Camp Borden, Ontario.				H.Q. FILE				
A/C Harvard		No. 2612		CRASH CAT. D.2		SE <input checked="" type="checkbox"/>		ME		DAY <input checked="" type="checkbox"/> NIGHT		
TYPE Harvard		No. 2623										
NAME			RANK		NO.		DUTY		INJURIES			
Humphrey, L.W. (2612)			LAC		R63744		P		Uninjured			
Not Stated												
Thompson (2623)			LAC		R15789		P		.			
									SERIOUS			
									FATAL			
									INJURY			
									CARD SERIAL NO.			
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		
Harvard		2612		Slight								
Harvard		2623		None								
Wasp												
Wasp												
SIGNAL No. & DATE			UNIT No. & DATE			COM. No. & DATE			REPORT		FILE	
5 25-12-40			4216 25-12-40									
NATURE OF ACCIDENT												

TYPE OF A/C

TYPE OF ENGINE

CATEGORY

MISCELLANEOUS CAUSES

STAGE OF FLIGHT

- TECH.
- DISOB.
- NEG NCE
- INEXP NCE
- MISCEL.
- INSTRUCT
- FLT CONTR.
- OTHERS
- PRIMARY
- FL. CONTR.
- MOV. SURFS.
- STAR SURFS.
- W. STRUTS
- LAND GEAR
- FLOATS
- FUSE OR HULL
- TAIL SKID OR W.
- ENGINE MOUNT.
- MISCEL.
- UND TD
- PRIMARY
- FUEL SYS.
- COOL SYS.
- IGNIT. SYS.
- LUB'N SYS.
- ENG. STR.
- AIRSCREW A.
- ENG. CONTR.
- MISCEL.
- UND TD

- UND TD
- PRIMARY
- HAND O.
- INSTS.
- WEATHER
- DRINKS.
- AL'S SURF.
- OTHER
- UND TD
- PRIMARY
- TAXIING
- LANDING
- TAKE-OFF
- FLIGHT
- STATRY
- FATAL
- INJ.
- 300
- 50

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15
- 16
- 17
- 18
- 19
- 20
- 21
- 22
- 23
- 24
- 25
- 26
- 27
- 28
- 29
- 30
- 31
- 32

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15
- 16
- 17
- 18
- 19
- 20
- 21
- 22
- 23
- 24
- 25
- 26
- 27
- 28
- 29
- 30
- 31
- 32

DUTY ON WHICH ENGAGED:

Formation flying.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Collision in air while changing position in formation.

COURT OF INQUIRY, INVESTIGATING OFFICER  
OR COMMANDING OFFICER'S REPORT:

MULT

ICA/PCL  
ICA/RA

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE: Inaccurate flying on the part of LAC Humphrey in Harvard 2612 in that he allowed the starboard mainplane of his machine to collide with the aileron of Harvard 2623 while changing position.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_