

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
To start up engine.	OR COMMANDING OFFICER'S REPORT: Investigation Officer's Report
Cpl. Atkins who was at the controls ran the engine up and a/c began to move forward, entered the hanger swerving to the left and hitting	DATE: 18-5-42  COMPOSITION: G.C. E.C. Emmett M.C., D.F.C. No. 41 S.F.T.S.  RECOMMENDATIONS:  That orders be issued prohibiting the running up of aircraft engines in front of open hangers.
on the part of the fitter.	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  Nil  Conclusion of A.I.B.  Aircraft being run up be ground crew, moved forward entered a hanger, ran into packing cases, airscrew smashing loose timbers on top of cases.  The fitter in control was careless and slow in action.  RECORDED BY DATE
	CHECKED BY DATE