

## CASPIR Aircraft Accident Cards

---

**Serial:** 3262

**Title:** North American Harvard Mk.IIB serial:3262 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-June-27. Harvard II s/n 3262. This accident involved 1 person. Cornwell W

**Keywords:** RAFHarvard II,3262,34 SFTS,34 Service Flying Training School,Dewinton Alberta,1943-June-27,CornwellRCAF L20

**Created:** 1943-06-27

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#3262>



PURPOSE OF FLIGHT:

Solo cross country

TECHNICAL OFFICER'S REPORT:

Priming pump leaking badly.

NATURE OF ACCIDENT:

In vicinity of DeWinton engine priming pump started to leak badly & pupil was forced to make a landing at DeWinton. The pump was repaired & the pupil received permission from Base to carry on with his cross country.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

58. Precautionary landing

SECONDARY OR CONTRIBUTORY FACTORS:

33. Technical defect

ACTION TAKEN: