

CASPIR Aircraft Accident Cards

Serial: 2729

Title: North American Harvard Mk.II serial:2729 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-November-16. Harvard II s/n 2729. This accident involved 2 people. Wilson RW, Zeman

Keywords: RAFHarvard II,2729,34 SFTS,34 Service Flying Training School,Aerodrome,1943-November-16,Wilson,ZemanRCAF L20

Created: 1943-11-16

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2729>

PURPOSE OF FLIGHT:

Circuits and landings.

NATURE OF ACCIDENT:

Engine caught fire while being started. Fire was extinguished.

TECHNICAL OFFICER'S REPORT:

Fracture of priming pipe due to chafing at forward wall owing to non-fitment of rubber bushing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

33. Technical defect.

SECONDARY OR CONTRIBUTORY FACTORS:

42. Fire after landing.

ACTION TAKEN:

Disciplinary action will be taken and special inspection of alla/c being undertaken.