

	DUTY ON WHICH ENGAGED: Solo Landings NATURE OF ACCIDENT AND STAGE OF FLIGHT: The pilot put the undercarriage lever in the down position but the starboard warning light remained red and on throttling back the Warning horn sounded. The pilot then completed one more circuit during which he made every effort ENTRECARS: to ensure that the undercarriage was locked in the Down Position before landing. PRIMARY CAUSE: Undercarriage locking pin failed to engage. Threre was no ascertainable cause for this failure. The starboard wheel collapsed after the landing run was completed.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: Commanding Officer's Report. DATE: 26-2-41 COMPOSITION: Group Captain (A.L. James.) RECOMMENDATIONS: ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	\cdot)
		RECORDED BY DATE	· • • • • • • • • • • • • • • • • • • •
ر ر ر		CHECKED BY DATE)))