

/ ) )	DUTY ON WHICH ENGAGED: Solo navigation flight. Practising steep turns & single engine procedu	OR COMMANDING OFF	Officer's REPORT:  Commanding Officer	- Colombo - Elevala	)
3	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: COMPOSITION:	5-3-41.		,
<b>7</b>	Forced down by adverse weather	COMPOSITION:	FB/AOF	P/Acn/ES/PM/I	4/I
•	conditions. While practising above		Wing Commander	r (W.W. Brown)	)
,	exercises his port engine quit.	RECOMMENDATIONS:			)
,	Pilot carried out forced landing.	RECOMMENDATIONS:			)
)					<b>う</b>
)	PRIMARY CAUSE:				)
0	Cpl. McEvoy throttled back while letting down through overcast.				<b>)</b>
)	Ice formed in his port carburettor				<b>)</b>
)	and the engine ceased firing.	ACTION TAKEN:	B) TECHNICAL (C) OT	urb	7
)		(II) DISSILLITARI	, D) 12011111111 (0) 01		5
)					)
)	*				)
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:				)
)	With his limited experience, Cpl				<b>3</b>
)	McEvoy was in error in allowing		ï	RECORDED BY	DATE
)	to get above solid overcast.				:
) 	ר כ כל כ כ כ כ כ כ כ כ כ כ	)))))	) ) ) ) )	CHECKED BY	DATE )