

TYPE OF A/C		CAUSES OF ACCIDENTS				CAUSES OF ACCIDENTS			
UNIT # 33 S.F.T.S.		COM. 2		PLACE Carberry Aerodrome, Man.		DATE 6-3-41		TIME 1710	
Carberry, Manitoba		2		Carberry Aerodrome, Man.		H.O. FILE 1300-29-26			
A/C TYPE Anson Harvard		NO. W1843 2926		CRASH CAT. C.7 D.		SE ME <input checked="" type="checkbox"/> DAY <input checked="" type="checkbox"/> NIGHT <input checked="" type="checkbox"/>			
NAME		RANK		NO.		DUTY		INJURIES	
Pinion, L.		W1843 LAC		904631		PP		Uninjured	
Kennatt, L.G.		2926 Sgt.		742309		PI		Uninjured	
Welch, N.A.		2926 LAC		126659		PP		Uninjured	
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL NO.	
Anson W1843		2926		Serious		D.14			
Harvard 2926				Slight		D.14			
Cheetah(2)				Serious		D.14			
Wasp S3M				Slight		D.14			
SIGNAL NO. & DATE		UNIT NO. & DATE		COM. NO. & DATE		REPORT		FILE	
264 8-3-41		A 59 8-3-41							
NATURE OF ACCIDENT									

CAUSES OF ACCIDENTS
 MISCELLANEOUS
 FLIGHT OF
 TAKEOFF
 LANDING
 TAXIING
 PRIMARY
 UND'TD
 OTHER
 ALG SURF.
 DRAGS.
 WEATHER
 INSTS.
 HAND O.

32 JU. 31
 30
 29
 28
 27
 26
 25
 24
 23
 22
 21
 20
 19
 18
 17
 16
 15
 14
 13
 12
 11
 10
 9
 8
 7
 6
 5
 4
 3
 2
 1
 19
 18
 17
 16
 15
 14
 13
 12
 11
 10
 9
 8
 7
 6
 5
 4
 3
 2
 1
 32
 31
 30
 29
 28
 27
 26
 25
 24
 23
 22
 21
 20
 19
 18
 17
 16
 15
 14
 13
 12
 11
 10
 9
 8
 7
 6
 5
 4
 3
 2
 1
 19
 18
 17
 16
 15
 14
 13
 12
 11
 10
 9
 8
 7
 6
 5
 4
 3
 2
 1

TECH.
 DISOB.
 NEG NCE
 INEXP NCE
 MISCEL.
 INSTRUCT.
 FLT CONTR.
 OTHERS
 PRIMARY
 FL CONTRS.
 MOV SURFS.
 STAB SURFS.
 W. STRUTS
 LAND GEAR
 FLOATS
 FUSE OR HULL
 TAIL SKID OR W.
 ENGINE MOUNT.
 MISCEL.
 UND'TD
 PRIMARY
 FUEL SYS.
 COOL SYS.
 IGNIT. SYS.
 LUB'N SYS.
 ENG. STR.
 AIRSCREW A.
 ENG. CONTRS.
 MISCEL.
 UND'TD
 PRIMARY

DUTY ON WHICH ENGAGED:

No training flight

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

Commanding Officer's Report.

DATE: 9-3-41

COMPOSITION: H.E. Walker Wg. Comdr.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Anson stopped on aerodrome with stopped airscrew. Harvard ran into it at end of landing run.

RECOMMENDATIONS:

LCA/PEL
LCA/AA

Continued an approach in view of the crowded state of the aerodrome

PRIMARY CAUSE:

Inexperienced instructor giving dual landing instruction.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Sgt. Kennett being held under a further period of supervision before being recategorized.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

The instructor who was concentrating on objects on his left omitted to notice the stationary aircraft ahead of him.

RECORDED BY

DATE

CHECKED BY

DATE