

/	2))))))))))))))	1) 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
<i>,</i>	<i>,</i> , , , , , , , , , , , , , , , , , ,	Must -
)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
)	Night Flying Instruction	OR COMMANDING OFFICER'S REPORT:
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	Commanding Officers Report.
)	Incoming aircraft collided with	COMPOSITION:
)	a/c about to take off.	Wing Commander W. W. Brown.
•	Anson 1602 coming in to land	
,	collided with Anson 1725 that was	)
)	taxiing on the ground.	RECOMMENDATIONS:
)		Runways in use were such that it was not possible
,		to stop Anson 1725 from taxying out onto the
)	PRIMARY CAUSE:	runway.
)	Failure of pilot to observe signal	A system is being adopted whereby the control
`	from control tower.	officer will, in future be stationed at the
J	O.C. considers that the controller	taxying post. The pupil is not being disciplined.
)	was not really in a position to give	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
γ´	a red signal to the pilot on the gr	
,	because he was too far E.W. runway.	,
)		$\mathcal{O}_{\mathcal{O}}$
)		<b>)</b>
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	)
`	Anson 1602 collided with Anson 1725.	
,	Runways in use were such that it was	i i
)	not possible to stop Anson 1725 from	)
	taxying out onto the runway.	· ·
`		CHECKED BY DATE
)		[]