

DUTY ON WHICH ENGAGED:

Dual instruction

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

While waiting to take off, Harvard 2705 ground looped off runway and collided with Harvard 2812. Air-screw, engine, probably engine mount and starboard wing damaged.

PRIMARY CAUSE:

Collision on ground.

LOSS OF CONTROL BY PILOT OF HARVARD 2705
WHILE LANDING.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

MULT
ACA/RSS
TCA/YA -

MONTHLY ACCIDENT RETURN.

DATE:

COMPOSITION:

RECOMMENDATIONS:

B 11

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____