

2011	ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER LS/PSS	
DUAL	INSTRUCTION	OR COMMANDING OFFICER'S REPORT	
)	RE OF ACCIDENT AND STAGE OF FLIGHT:	MONTHLY ACCIDENT RETURN.  DATE:  COMPOSITION:	
GROUN TEMPO	DE LOOPED WHILE LANDING. THE PILOT	· .	
WING	TTING THE A/C TO GROUND LOOP. THE PORT TIP, AILERON, AND OUT BOARD AILERON HINGE PAMAGED	RECOM MENDATIONS:	
PRIMA	RY CAUSE:		
GROUND	LOOP DUE TO INEXPERIENCE OF PUPIL		
,		ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
SECON	DARY CAUSE OR CONTRIBUTING FACTORS:		
PILOT	FAILED TO CORRECT SWING INTIME TO PREVENT		
GROUN	D L00P.	- RECORDED BY DATE	_