

```
00000
 DUTY ON WHICH ENGAGED:
                                       COURT OF INQUIRY, INVESTIGATING OFFICER
                                       OR COMMANDING OFFICER'S REPORT:
General Reconnaissance exescise.
                                                            Commanding Officers Report.
 NATURE OF ACCIDENT AND STAGE OF FLIGHT:
                                       DATE:
                                                            5-4-41
Landing on a runway that had high
                                       COMPOSITION:
snow banks on the side and ice on
                                                            Group Captain E.A. Blake.
the runway. Pilot expecting to drift
to starboad he landed to the port side
of the runway, his left wheel touching commendations:
portion of the ice which heeved hims
                                                    The pilot was landing under difficult
to the left. Correcting with port
                                                    conditions and it is considered that his
 management engine the tail plane touched
                                                    error was anexcusable one. It is not
             the snow bank, and the a/c was
                                                    considered that there is need for a Court
 thrown momentarily out of control, the
                                                    of Inquiry as the cause of the accident
 left wheel mounting the snow bank.
                                                    is abvious. No disciplinary action is
 PRIMARY CAUSE.
                                       ACTION TAKEN:
                                                    recommended.
                                         (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
 Error of judgment on the part of the
 pilot while making a cross wind landing
 on a runway banked high with snow at
 sides and an icy surface.
 SECONDARY CAUSE OR CONTRIBUTING FACTORS:
 The a/c got out of control after touching
 the port side of it's tail plane and the
                                                                    RECORDED BY
 port wheel on the snow bank after sleeving .
 slightly to the left due to ity runway.
                                                                    CHECKED BY
```