

DUTY ON WHICH ENGAGED:

RETURNING TO BASE AFTER FLYING
OPERATIONS AT EMERGENCY FIELD AT
HAGERSTVILLE

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Engine refused to take throttle after aircraft had completed slow roll. Pilot carried out successful forced landing without damage to aircraft, personnel or property.

DATE:

COMPOSITION:

FB/AOP/ES/IM/AVC

RECOMMENDATIONS:

PRIMARY CAUSE:

Cause of forced landing was failure of engine to take throttle after aircraft had completed slow roll to the right.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Carburettor inspected and fault rectified.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE