

TYPE OF A/C		CAUSES OF ACCIDENTS		ENGINE FAILURE	
UNIT	# 33 S.F.T.S. Carberry Man.	COM.	2	PLACE	Carberry
A/C TYPE	Anson	No.	9638	CRASH CAT.	D2
NAME		RANK	No.	DUTY	INJURIES
Dowdell E.F.		LAC	1256394	PP	Uninjured.
TYPE A/F & ENGINE		No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.
Anson		9638	Slight		
Cheetah		23363/139184			
Cheetah		23362/139178			
SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE	
REPORT		FILE		DATE	
NATURE OF ACCIDENT					

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Forced landing practice.

OR COMMANDING OFFICER'S REPORT: **TLO/PCT**

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Monthly Accident Return.

COMPOSITION:

**Aircraft struck a cable height
recorder and tore part of trailing
edge of wing-tip.**

RECOMMENDATIONS:

**7 days stoppages of privileges awarded to pupil
Orders issued to taxiing on tarmac without
airman on each wing.**

PRIMARY CAUSE:

**Narrow width of taxi strip from
No. 1 Hangar**

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

**Aircraft struck aerdale height
recorder.**

RECORDED BY

DATE

CHECKED BY

DATE