

TYPE OF A/C		CAUSES OF ACCIDENTS				STAGE OF FLIGHT			
TYPE OF ENGINE		NATURE OF ACCIDENT				MISCELLANEOUS CAUSES			
PILOT		OTHERS		AIRFRAME FAILURE		ENGINE FAILURE			
UNIT # 9 S.F.T.S.		COM. 3		PLACE AERODROME SUMMERSIDE, P.E.I.		DATE 1-6-41		TIME 0015	
SUMMERSIDE, P.E.I.						H.O. FILE 1100-23-77			
A/C TYPE HARVARD II		No. 2877		CRASH CAT. C.2		SE X		ME	
						DAY		NIGHT X	
NAME		RANK		No. DUTY		INJURIES		SERIOUS	
LIGGETTE, J.L.		LAC		R78131 P		UNINJURED		FATAL INJURY	
								CARD SERIAL NO.	
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.	
DATE		HOURS FLOWN BY PILOTS							
HARVARD 2877		SLIGHT							
WASP 8544/4403		SLIGHT							
HI									
INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS.			
DUAL SOLO		DUAL SOLO		136					
SIGNAL No. & DATE		UNIT No. & DATE		COM. No & DATE		REPORT		FILE	
DATE		A.397 1-6-41							

NATURE OF ACCIDENT

MISCELLANEOUS CAUSES  
 UND'TD  
 PRIMARY  
 HAND O.  
 INSTS.  
 WEATHER  
 DRKNS.  
 A/G SURF.  
 OTHER  
 UND'TD  
 PRIMARY  
 TAXING  
 LANDING  
 TAKE-OFF  
 FLIGHT  
 STAIRY  
 FATAL  
 INJ.  
 3RD.  
 5.  
 26

TECH.  
 DISOB.  
 NEG'NCE  
 INEXP'NCE  
 MISCEL.  
 INSTRUCT.  
 FLT. CONTR.  
 OTHERS  
 PRIMARY  
 FL. CONTRS.  
 MOV. SURFS.  
 STAB. SURFS.  
 W. STRUTS  
 LAND. GEAR  
 FLOATS  
 FUSE OR HULL  
 TAIL SKID OR W.  
 ENGINE MOUNT.  
 MISCEL.  
 UND'TD  
 PRIMARY  
 FUEL SYS.  
 COOL. SYS.  
 IGNIT. SYS.  
 LUB'N SYS.  
 ENG. STR.  
 AIRSCREW A.  
 ENG. CONTRS.  
 MISCEL.  
 UND'TD

31  
 30  
 29  
 28  
 27  
 26  
 25  
 24  
 23  
 22  
 21  
 20  
 19  
 18  
 17  
 16  
 15  
 14  
 13  
 12  
 11  
 10  
 9  
 8  
 7  
 6  
 5  
 4  
 3  
 2  
 1

19  
 18  
 17  
 16  
 15  
 14  
 13  
 12  
 11  
 10  
 9  
 8  
 7  
 6  
 5  
 4  
 3  
 2  
 1  
 26

DUTY ON WHICH ENGAGED: FLYING SEQUENCES 7 & 8. COURT OF INQUIRY, INVESTIGATING OFFICER  
OR COMMANDING OFFICER'S REPORT: ✓

LUC/PCDUF/UCDL

NATURE OF ACCIDENT AND STAGE OF FLIGHT:  
PILOT NEGLECTED TO LOWER UNDERCARRIAGE FOR  
LANDING.

DATE:  
COMPOSITION:

**Monthly Accident Return.**

RECOMMENDATIONS:

**More instructions.**

PRIMARY CAUSE: FAULTY COCKPIT DRILL ON CIRCUIT.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

**Aircraft landed with u/c up.**

RECORDED BY

DATE

CHECKED BY

DATE