

CASPIR Aircraft Accident Cards

Serial: V3291

Title: Airspeed Oxford Mk. I serial:V3291 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 2 aircraft on 1941-June-26. They are: Oxford s/n AR780, Oxford s/n V3291. This accident involved 1 person. Rath HE

Keywords: RAFOxford ,V3291,34 SFTS,34 Service Flying Training School,Aerodrome,1941-June-26,RathRCAF L20

Created: 1941-06-26

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#V3291>

DUTY ON WHICH ENGAGED:

Solo flying

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft swung while taking off and collided with stationery aircraft No. V 3291

DATE:

Monthly Accident Return.

COMPOSITION:

~~MULT~~
OCA/PSS
~~MA/KA~~

RECOMMENDATIONS:

All pupils lectured by C.F.I. on correct action to take if an a/c swings & the uselessness of relying and manipulating the throttles to keep the a/c straight.

PRIMARY CAUSE:

Pilot failed to correct swing while taking off.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Collided with another aircraft while trying to manipulate the throttles to stop swing.

RECORDED BY

DATE

CHECKED BY

DATE