

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
NIGHT FLYING TRAINING  NATURE OF ACCIDENT AND STAGE OF FLIGHT:  CRASHED INTO GROUND AND BURST INTO FLAMES AFTER TAKE OFF	OR COMMANDING OFFICER'S REPORT:  COURT OF INQUIRY  DATE: 23-7-41  COMPOSITION:  PRESIDENT - S/L PATTISON, R.V.L.  MEMBER - F/L BANNOCK, R.  MEMBER - F/O TURNER, R.D.  RECOMMENDATIONS: EMPHASIS SHOULD BE PLACED ON THE IMPORTANCE OF
PRIMARY CAUSE: INABILLITY OF PILOT TO MAINTAIN EQUILIBRIUM BY INSTRUMENTS.	ALLOWING THE MINIMUM TIME OF SEVEN MINUTES AT 1500 R.P.M. AFTER STARTING THE ENGINE TO ENSURE THAT THE GYRO INSTRUMENTS ARE PROPERLY ERECTED BEFORE TAKING-OFF AT NIGHT.  PUPIL PILOTS SHOULD BE GIVEN DUAL IN THE COCKPIT FROM WHICH THEY ARE TO FLY THE AIRCRAFT SOLO AT NIGHT WHEN CONVERTING TO A NEW TYPE.  ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	N I L
CRASHED TO GROUND AND BURNED.	RECORDED BY DATE
	)