

/			
1)))))))))))))))))))	> >) +
)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER R.C.A.F. L.20)
)	NIGHT FLYING SOLO	OR COMMANDING OFFICER'S REPORT:	7
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	OR COMMANDING OFFICER'S REPORT: DATE: COMPOSITION: H. Q. 885-L-20 UOK/B)
)	PHIOT MEDICATED TO TURN PETROL COOK	COMPOSITION:	•
•	PILOT NEGLECTED TO TURN PETROL COCK TO FULL ON POSITION NECESSITATING A	00.98	3
•	FORCED LANDING DURING TAKE OFF. Pilot		. J
`	landed, plane continued along the	RECOMMENDATIONS:)
. <u> </u>	ground and passed over the railway	· · · · · · · · · · · · · · · · · · ·)
)	and through the fence damaging both wings, touched the highway	Flashlights which might have prevented this accident were demanded on July 4.	
)	PRIMARY CAUSE: and hit embarkment on	Demand No. A86 and have not yet been	a
)	west side of roadway. INCORRECT COCKPIT PROCEEDURE DUE TO	received.	7
•	CARELESSNESS OF PILOT		7
``		ACTION TAKEN:	J <u>⊾</u>
<u>ر</u>		(A) DISCIPLINARY (B) TECHNICAL (C). OTHER	3
J		Log Book Endorsed.)
)) .
)			3
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:))
`	FORCED LANDING	•	ر -
`		RECORDED BY DATE)
<u>ر</u>			
)		CHECKED BY DATE	•
))))))))))))))))))))))))))))))	3
	<u> </u>		