

DUTY ON WHICH ENGAGED:

SOLO PRACTICE TAKE OFFS AND LANDINGS

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

PILOT OF 6188 TAXIED UP BEHIND 2004 WHICH WAS STOPPED ON TAXI STRIP AND FAILED TO STOP IN TIME - STRUCK RUDDER WITH LEFT WING

PRIMARY CAUSE:

ERROR IN JUDGEMENT OF PILOT OF 6188

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

WING OF 6188 STRUCK RUDDER OF 2004

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

R.170

DATE:

COMPOSITION:

MULT
TCA/PCT
TCA/XA

RECOMMENDATIONS:

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Disciplinary action taken

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____