

NDING UNDER BAD WEATHER CONDITIONS. WHILE KING A TURN AT NIGHT AT LOW ALTITUDE, THE AVERT OF THE REST WING-TIP REPORT OF THE GROUND RESULTING IN A CRASH-RIMARY CAUSE: AD WEATHER . WHILE MAKING A TURN AT NIGHT OF LOW ALTITUDE THE AVE LOST FURTHER ALTITUDE THE RIGHT WING-TIP STRUCK THE GROUND ESULTING IN A CRASH-	MINIMUM FLYING WEATHER CONDITIONS OF CEILING AND VISIBILITY OF 600° AND THREE MILES BY DAY AND 1000° AND 5 MILES BY NIGHT BE LAID DOWN FOR THIS AIRPORT AND ADHERED TO EXCEPT IN CASE OF EMERGENCY.
CONDARY CAUSE OR CONTRIBUTING FACTORS: RCRAFT OVERSHOT A ERODROME AND CRASHED	RECORDED BY DATE