

-			
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	<u>.</u>	)
Practice spinning, stalling	OR COMMANDING OFFICER'S REPORT:	D-14	<b>/</b> 1
and turns.		,	<b>√</b> ′
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:		. )
Brakes were released after complete	COMPOSITION:		)
cockpit check and a/c began to			,
move forward. Stbd oleo leg			J
collapsed.			)
	RECOMMENDATIONS:		)
			,
PRIMARY CAUSE:			
5. U/C drill on take-off.			`
Suspected that U/C selector lever			,
was moved back from notch in down			)
position and locking plunger was	ACTION TAKEN:		)
thus pulled out of engagement.	(A) DISCIPLINARY (B) TECHNICAL (C) OTI	łER	
11 0 -1			)
1. day			)
•			1
			. ,
SECONDARY CAUSE OR CONTRIBUTING FACTORS:			ì
Throttle apparently open enough to		ECORDED BY	
prevent horn blowing.	ĸ	TCORDED BI	DATE
33 11/0 D-10 - 33 C		i	
R.C. AF CRIN L20 REQ. 1247 10M-15-11-41	ound	HECKED BY	DATÉ )
		<b>,</b> , , , , , ,	
			, , , ,