1,,			RERAME	FAIL		ENG!		Mo Nictinio
V V	\ <u></u>	CAUS			CCIDENTS			
P	UNIT 1 S.F.T.S. COM.	PL/	ACE				43 TIME1030	1 1 / /9'/
ΡE	Camp Borden 1		Aerodro	me.		H.Q. FILE 11	.00-26-38	Z THER
Τ	A/C TYPE Harvard]]	No	2638		CRASH CAT. Cl	SE ME	DAY NIGH	0 2/25/
丄	NAME	RANK	No.	; <u>.</u> TY	וענאו	RIES	SERIOUS	DE ORTENA
	Badland, A.F.	P/0	J14 062	FI	Uninj.		FATAL !NJU	S > P
PE OF ENGINE	0						CARD SERIAL NO	O S SUPPRES
1≿	TYPE A/F NO. EXTENT & ENGINE NO. OF DAMAG	REPO		DAT	но	URS FLOWN E	BY PILOTS	1 1 / 8/
	1 0/30		RM No.		INST. NIGHT	ON TYPE		10s. 7 - 66
GORY	4376/8517 saight	-						A O M CONTACT OF STATE OF STAT
ATE	и п	DATE	сом.	No. & E	ATE REPOR	₹T FI	LE DATE	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

	n practice.	COURT OF INQUIRY, INVESTIGATING OFFI OR COMMANDING OFFICER'S REPORT:	<u>CER</u>)
Overshot hit soft a/c went	accident and stage of flight: aerodrome on landing spot on far boundary and up on its nose. Pilot	DATE: COMPOSITION:	D-14)
	go around again but ailed to catch.	RECOMMENDATIONS:)
) PRIMARY CA				
	lvershat	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C)	OTHER)
))		Log book endorsed and logge)
SECONDARY Bad surfe	CAUSE OR CONTRIBUTING FACTORS:)
))			RECORDED BY DATE	,
) R.C.A.F. FORM I	.20 REQ. 1247 10M-15-11-41		CHECKED BY DATE)
() () () () () ()			· · · · · · · · · · · · · · · · · · ·)