		S. JARS ITS SE	0 135 15 15 15 15 15 15 15 15 15 15 15 15 15	i da noiti	**************************************	2 42 48	STA REALTHA	ST Jui Par
O		IRFRAME	FAILU	RE		INE FA	ILURE	1   kr/10°/
E OF A	UNIT 41 S.F.T.S., COM.	PLACE Calg	en, U.S	CIDENTS_		2-43 TIME		1 1 / .6. /
TYPE	Hey builly buokt	No. <b>2956</b>		RASH 1. C 7	SE M		ыёнт	S WERT
	NAME RAN		DUTY	INJUF	≀ I E S	si	ERIOUS	C A C SUR!
E OF ENGINE		145546	2 PP	Ni 1		SE	CARD RIAL NO.	S O CHE
ΥP	> <del></del>	EPORT SERIAL		ног	JRS FLOWN	BY PILOTS		11 1/8/
_	& ENGINE NO. OF DAMAGE	FORM No.	DATE	INST, NIGHT	ON TYPE	TOTAL	LASI	
ORY	Harvard 2956 Serious Wasp Y256/5054 Slight.							
TEGO	SIGNAL NO. & DATE UNIT NO. & DAT	re com	, No. & DA	TE REPOR	RT	FILE	DATE	TO STORY

)	) ) ) ) ) ) <b>) ) ) ) ) ) ) ) ) ) )</b>	<b>つつつつつつ /っっ</b>	<b>)</b> ) ) ) ) )	· ) ) ) )
)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFI	CER	. )
)	Steep turns and forced landings.	OR COMMANDING OFFICER'S REPORT:	<del></del>	
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT: Improper use of gas tap caused engine to stall. Pilot made	DATE: COMPOSITION:	(out)	)
)	wheels up landing. Forced landing was carried out when pilot became lost.	RECOMMENDATIONS:		)
) ) )	PRIMARY CAUSE: 51. Lost. 17. Forced Landing			)
)	0	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C)	OTHER	)
)		Pilos Error		)
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:			)
)	U/c retracted landing. It is considered that this accident was		RECORDED BY	DATE )
)	caused by faulty manipulation of fuel tap.  R.C.A.F. FORM 120 REQ. 1247 10M-15.11.41		CHECKED BY	DATE )
)			) ) ) ) ) )	DATE J