

3064

HARVARD II

1941

S E TRAINER

REGISTRATION NO.

MAKE & MODEL

YEAR

TYPE

MANUFACTURERS No.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
3.5.44	1	Wardrup Aviation				20.10.44	SR. # 3TC
2 Dec 47	2	See remarks	W.P. 14		3049.00 176.05	1 May 48	CAN
29 May 56	3	for embodiment	ALL	572862		2 May 56	R CN
	4	554-68/14+68/5				2 May 56	SR 6RD
27 Nov 52	5	for embodiment	W.P. 14				
25 Nov 52	6	for embodiment	14-1C	572862			
	7						
	8						
	9						
	10						
	11						
	12						

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
25.6.42	C5	Weymouth	1345	148775 SR 154	26/6	J Kernan	Solo		
	2								
	3								
	4								
	5								
	6								
	7								
	8								

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re. acc. 1 - C struck ground heavily due to poor judgement of pilot
 28/9/47. 68/5 - 24.6.48 (TSO) no radio, when on complete
 2 Dec 47. No modification to Spec. R.M. 1-1 and re-positioned to
 Spec. R.M. 1-1 - App. "B" - & full out. App. 3.46.48
 1 May 48. Equipped with field fittings
 1 May 48 TSN 3056158 T.S. O/H 177:35
 31 May 49. App. T.S. 17 - 3503.58, -TSO 625.00
 25 Nov 52. radio compass MN 31 installed.

