

3069 | HARVARD II | 1941 | SE TRAINER  
 REGISTRATION NO. | MAKE & MODEL | YEAR | TYPE | MANUFACTURERS NO.

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N NO.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1.10.48		Noorduyn Aviation				34.44	2 ITC
7.2.52	Reconditioning mod. RMI-7	CPA	501661			1.8.52	SR6R
3.1.52	prototyping of additional mod.	C. Co. July 27, 1951	AMC Letter 511763 (4046) 13 Nov.				
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV
4.4.21	"C1"	Rockcliff Aerod	1600	CJSS A745	10/4	P/O J.P. Howard	1		
2									
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re. Acc. 1 - When taxiing for take off a/c taxied into Harvard 2785' causing small dent to door  
 22/12/48 Allotted to 6 RD for ATR II installation  
 2333.70 740.00  
 March 49 - a/c rep. 2385.05, TSO-791.50  
 5.5.51 - a/c selected - 24 unit prototypes - 11 TSO's @ 688 d 2 May - file 388 JW 501664

