

3818

HARVARD II

1941

S.E. TRAINER

REGISTRATION No.

MAKE &amp; MODEL

YEAR

TYPE

MANUFACTURERS No.

## OVERHAUL DATA

| DATE | REASON | DONE BY | REQ'N. No. | COST | HOURS SINCE NEW | DATE COMPLETED | ALLOTMENT |
|------|--------|---------|------------|------|-----------------|----------------|-----------|
| 1    |        |         |            |      |                 |                |           |
| 2    |        |         |            |      |                 |                |           |
| 3    |        |         |            |      |                 |                |           |
| 4    |        |         |            |      |                 |                |           |
| 5    |        |         |            |      |                 |                |           |
| 6    |        |         |            |      |                 |                |           |
| 7    |        |         |            |      |                 |                |           |
| 8    |        |         |            |      |                 |                |           |
| 9    |        |         |            |      |                 |                |           |
| 10   |        |         |            |      |                 |                |           |
| 11   |        |         |            |      |                 |                |           |
| 12   |        |         |            |      |                 |                |           |

## ACCIDENT RECORD

| DATE    | CATEGORY | PLACE                 | TIME | REPORT REFERENCE | DATE  | RANK & NAME OF PILOT | No. IN CREW | DISPOSAL | DATE SERV. |
|---------|----------|-----------------------|------|------------------|-------|----------------------|-------------|----------|------------|
| 27.9.41 | "A"      | Yorktown Maine A.     | 0355 | 115713 s. A194   | 27/9  |                      |             |          |            |
| 28.10.  | "B"      | R.1 Yorktown Maine A. | 1500 | 115713 s. A230   | 28/10 | LAC S.R. Collins     |             |          |            |
| 3       |          |                       |      |                  |       |                      |             |          |            |
| 4       |          |                       |      |                  |       |                      |             |          |            |
| 5       |          |                       |      |                  |       |                      |             |          |            |
| 6       |          |                       |      |                  |       |                      |             |          |            |
| 7       |          |                       |      |                  |       |                      |             |          |            |
| 8       |          |                       |      |                  |       |                      |             |          |            |

B. S. LTD.

## AIRCRAFT RECORD CARD

PAT'D 1920

## REMARKS

Re acc #1 - #2 TC. s T609 8/10/41 advised the crash category Swing  
 Re acc 2 - Eng. installed 9256/4644. Ground loops - pilot failed to correct

