CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: AJ898

Title: North American Harvard Mk. II serial:AJ898 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-January-26. Harvard II s/n AJ898. This accident involved 2 people. Kjeldbech J, Middleton PF

Keywords: RAFHarvard II,AJ898,39 SFTS,39 Service Flying Training School,Swift Current,1942-January-26,Kjeldbech,MiddletonRCAF L20

Created: 1942-01-26

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ898

PILOT | OTHERS | AIRFRAME FAILURE | ENGINE FAILURE

CAUSES OF ACCIDENTS

PILOT: JUL. | TECH. | DISOB. | NEG'NCE | INEXP'NCE | MISCEL. | INSTRUCT. | FLT. CONTR. | OTHERS

AIRFRAME FAILURE: PRIMARY | FL. CONTS. | MOV. SURFS. | STAB. SURFS. | W. STRUTS | LAND. GEAR | FLOATS | FUSE. OR HULL | TAIL SKID OR W. | ENGINE MOUNT. | MISCEL. | UND'TD

ENGINE FAILURE: PRIMARY | FUEL SYS. | COOL. SYS. | IGNIT. SYS. | LUB'N SYS. | ENG. STR. | AIRSCREW A. | ENG. CONTS. | MISCEL. | UND'TD

MISCELLANEOUS CAUSES: PRIMARY | HAND'G. | INSTS. | WEATHER | DRKNS. | A'G'D SURF. | OTHER | UND'TD

STAGE OF FLIGHT: TAXYING | LANDING | TAKE-OFF | FLIGHT | STAT'RY

INJURY: FATAL | INJ. | 3RD.

UNIT	COM.	PLACE	DATE	TIME
39 S.F.T.S. Swift Current	4	Swift Current	26-1-42	2005

H.Q. FILE 1300-AJ898

A/C TYPE	No.	CRASH CAT.	SE	ME	DAY	NIGHT
Harvard II	AJ898	C 4	x			x

NAME	RANK	No.	DUTY	INJURIES	SERIOUS: FATAL	SERIOUS: INJURY
Middleton, P.F.	F/O	62328	P.I.	Uninjured		
Kjeldbech, J.	LAC	785088	P.P	Uninjured.		

CARD SERIAL No.

TYPE A/F & ENGINE	No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE
Harvard	AJ898	Slight			
Wasp S3H1	A213783	Nil			

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE: DUAL	ON TYPE: SOLO	TOTAL: DUAL	TOTAL: SOLO	LAST 6 MOS.
49	11	2	82	120	481	
5	2	17	11	42	38	

SIGNAL No. & DATE	UNIT No. & DATE	COM. No. & DATE	REPORT	FILE	DATE
A 681 27-1-42					

NATURE OF ACCIDENT

TYPE OF A/C

TYPE OF ENGINE

CATEGORY: A | B | C | D

DUTY ON WHICH ENGAGED:

Night flying landings.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft swung on landing at night, and port wing tip hit the ground.

PRIMARY CAUSE:

~~Instructor failed to correct swing.~~

2. Swung

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:

DATE: R170 1-11-51 ✓

COMPOSITION:

RECOMMENDATIONS:

Nil

ACTION TAKEN:
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Instructor interviewed by C.I.

RECORDED BY DATE

CHECKED BY DATE