CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 6034

Title: Avro Anson Mk. I serial:6034 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1942-January-06. Anson s/n 6034. This accident involved 3 people. Drohan JD, Roche TJ, Rutherford MN

Keywords: RCAFAnson ,6034,1 AOS,1 Air Observer School,Delessips Field Weston,1942-January-06,Drohan,Roche,RutherfordRCAF L20

Created: 1942-01-06

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6034

PILOT | OTHERS | AIRFRAME FAILURE | ENGINE FAILURE

CAUSES OF ACCIDENTS

| | | |

DUTY ON WHICH ENGAGED:
Routine navigation flight.

COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:
Forced landing and hit fence.

DATE:
COMPOSITION: 20/AOP/ET/PM/M/I/UBF

Radio went dead. Airspeed ceased to function. One engine went dead whilec circling field and on landing aircraft crashed into fence.

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

1 Weather. ~~Brakes failed to hold after landing.~~

2 Icing of the carburretor.

17

17. Forced Landing

ACTION TAKEN:
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

To the best of our knowledge every precaution taken in this case.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Aircraft crashed into fence.~~

26

26 Engine Trouble - Accident

RECORDED BY DATE

CHECKED BY DATE