CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 6677

Title: Avro Anson Mk. I serial:6677 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 2 aircraft on 1942-May-06. They are: Harvard s/n 3108, Anson I s/n 6677. This accident involved 2 people. Murray D, Nairn JTD

Keywords: RCAFAnson I,6677,8 AOS,8 Air Observer School,Saint-Hubert Quebec,1942-May-06,Murray,NairnRCAF L20

Created: 1942-05-06

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6677

PILOT | OTHERS | AIRFRAME FAILURE | ENGINE FAILURE

CAUSES OF ACCIDENTS

PRIMARY, UND'TD, MISCEL., ENG. CONTS., AIRSCREW A., ENG. STR., LUB'N SYS., IGNIT. SYS., COOL. SYS., FUEL SYS., PRIMARY, UND'TD, FUSE. OR HULL, FLOATS, LAND. GEAR, W. STRUTS, STAB. SURFS., MOV. SURFS., FL. CONTS., PRIMARY, OTHERS, FLT. CONTR., INSTRUCT., MISCEL., INEXP'NCE, NEG'NCE, DISOB., TECH., JU., P

TYPE OF A/C | TYPE OF ENGINE | CATEGORY

MISCELLANEOUS CAUSES | STAGE OF FLIGHT

HAND G., INSTS., WEATHER, DRKNS., AL'G SURF., OTHER, UND'TD, PRIMARY, TAXYING, LANDING, TAKE-OFF, FLIGHT, STAT'RY

FATAL, INJ., 3RD., INJURY

UNIT	COM.	PLACE	DATE	TIME
8 AOS Ancienne Lorette	3	St. Eubert	6-5-42	2210

H.Q. FILE 1100-66-77

A/C TYPE	No.	CRASH CAT.	SE	ME	DAY	NIGHT
Harvard / Anson I	3108 - D / 6677	C 3		X		X

NAME	RANK	No.	DUTY	INJURIES	SERIOUS: FATAL	SERIOUS: INJURY
Murray D.	~~Lt.~~	587907	P.	Uninjured.		
Nairn J.T.D.		134222?6	P.	"		

CARD SERIAL No.

288

TYPE A/F & ENGINE	No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE	HOURS FLOWN BY PILOTS: INST.	NIGHT	ON TYPE: DUAL	ON TYPE: SOLO	TOTAL: DUAL	TOTAL: SOLO	LAST 6 MOS.
Harvard	3108											
Anson	6677	Slight				1	300	13	1275	30	1420	
Cheetah	As31893/11139											
	AS31926/11140											

SIGNAL No. & DATE	UNIT No. & DATE	COM. No. & DATE	REPORT	FILE	DATE
A-249 7-5-42					

NATURE OF ACCIDENT

DUTY ON WHICH ENGAGED:

Anson was waiting at taxi post to take off for Que. Harvard was proceeding to takeoff post.

COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: MULT ✓ R.170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Harvard 3108 taxied into ~~engine~~ ANSON 6677, Port wing contacted rudder and tail plane off Anson.

DATE: TCA/PCT

COMPOSITION: TCA/XA

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Pilot of Harvard 3108 failed to see tail navigation light of Harvard 6677 because tail light of Anson was very dim.~~

COLLISIONS

9

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

All pilots notified to hold morse Key down when changing from Steady to Morse, and ~~ready~~ keep it down until ready to signal. No Disciplinary action required.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C 3108 taxied into rear of A/C 6677.~~

RECORDED BY DATE

CHECKED BY DATE

R.C.A.F. FORM L20 REQ. 1247 10M—15-11-41