CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: AJ983

Title: North American Harvard Mk. II serial:AJ983 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-June-15. Harvard II s/n AJ983. This accident involved 1 person. Benwell RH

Keywords: RAFHarvard II,AJ983,39 SFTS,39 Service Flying Training School,Aerodrome,1942-June-15,BenwellRCAF L20

Created: 1942-06-15

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ983

PILOT | OTHERS | AIRFRAME FAILURE | ENGINE FAILURE

CAUSES OF ACCIDENTS

UNIT	COM.	PLACE	DATE	TIME
39 S.F.T.S. Swift Current	4	M.A.	15-6-42	1305

H.Q. FILE 1300-AJ983

A/C TYPE	No.	CRASH CAT.	SE	ME	DAY	NIGHT
Harvard 11	AJ983	C 1	x		x	

NAME	RANK	No.	DUTY	INJURIES	SERIOUS FATAL	SERIOUS INJURY
Benwell R.H.	LAC.	1318044	P.P.	Uninjured.		

CARD SERIAL No.

TYPE A/F & ENGINE	No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE
Harvard 11	AJ983	Slight			
Wasp 12167/A262237		Nil			

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE DUAL	ON TYPE SOLO	TOTAL DUAL	TOTAL SOLO	LAST 6 MOS.
14	4	35	34	63	67	

SIGNAL No. & DATE	UNIT No. & DATE	COM. No. & DATE	REPORT	FILE	DATE
A-701 16-6-42					

NATURE OF ACCIDENT

TYPE OF A/C | TYPE OF ENGINE | CATEGORY | CAUSES | MISCELLANEOUS | FLIGHT | STAGE OF | INJURY

DUTY ON WHICH ENGAGED:
Taxiing A/C into hanger.

COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:
Pupil taxied A/C into petrol bowser.

DATE:

COMPOSITION: TC 0/PCT ✓

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:
~~Carelessness.~~

9. Collisions (9)

ACTION TAKEN:
(A) Disciplinary (B) Technical (C) Other

Disciplinary action taken against pupil. (7 days C.C.)

SECONDARY CAUSE OR CONTRIBUTING FACTORS:
~~Pilot taxied aircraft into petrol bowser.~~

RECORDED BY DATE

CHECKED BY DATE