CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 11335

Title: Avro Anson Mk. II serial:11335 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-July-12. Anson II s/n 11335. This accident involved 2 people. Minot VT, Burton AW

Keywords: RCAFAnson II,11335,17 SFTS,17 Service Flying Training School,Low Flying Area,1943-July-12,Burton,MinotRCAF L20

Created: 1943-07-12

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11335

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
No.17 S.F.T.S. Souris, Man.	# 2	Low flying area 17 SFTS.	12-7-43	0830

H.Q. FILE 1100-113-35

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
Anson II	11335	C 7		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Burton, A.W.	F/O	J10590	PI	Nil
Minot, V.T. GB	F/S	905216	PP	Nil

SIGNAL

NO.	DATE
A27	12-7

D 14 (REVISED)

NO.	CHECKED
6	✓

21

ENGINE	ENGINE NUMBER (S)
Jacobs L6MB	P26170/10874 Nil S26191/10895 Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE		TOTAL	
		SOLO	DUAL	SOLO	DUAL
72	102	188	58	884	187
38	20	40	61	81	103

ACCIDENT CLASSIFICATION

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT'RY

INJURY
FATAL
INJ
3RD
S
N

PURPOSE OF FLIGHT:

Low Flying sequences

NATURE OF ACCIDENT:

Pupil was having difficulty in maintaining minimum altitude, when he suddenly pushed control column forward to follow contour and hit a tree which was in instructor's blind spot. Suddenness of action prevented instructor from correcting.

CLASSIFICATION:

32. Pilot error

SECONDARY OR CONTRIBUTORY FACTORS:

26. Collision in the air
14. Misuse of controls

TECHNICAL OFFICER'S REPORT:

Nil

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

ACTION TAKEN:

R.C.A.F. L 20 (REVISED)
7M-4-43 (3202) K.P. 5051
H.Q. 885-L 20

C. C. LTD. 7084-43