CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 6247

Title: Avro Anson Mk. I serial:6247 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-August-10. Anson I s/n 6247. This accident involved 4 people. Hall CSW, Mytruk W, Sule C, Swain GR

Keywords: RCAFAnson I,6247,1 CNS,1 Central Navigation School,Letellier Manitoba,1943-August-10,Hall,Mytruk,Sule,SwainRCAF L20

Created: 1943-08-10

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6247

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
1 C.N.S. Rivers	2	Near Letellier, Manitoba.	10-8-43	0952

H.Q. FILE 1100-62-47

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
Anson I	6247	C		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Mytruk, W.	F/S	R113287	P	Nil
Sule, C.	Sgt	R179713	WAG	Nil
Swain, G.R. GB	LAC	1399543	Nav	Nil
Hall, C.S.W.	LAC	GB1605862	Nav	Nil

SIGNAL

NO.	DATE
A172	11-8

D 14 (REVISED)

NO.	CHECKED
2	✓

#4

ENGINE	ENGINE NUMBER (S)
Cheetah IX	AS31263/ Nil
	AS15437 Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE		TOTAL	
		SOLO	DUAL	SOLO	DUAL
40	275	750	81	792	112

COMMAND

MONTH

STAGE OF FLIGHT: FORCED LANDING, TAXYING, LANDING, TAKE-OFF, FLIGHT, STAT'RY

INJURY: FATAL, INJ., 3RD, S

TYPE OF A/C

TYPE OF UNIT

CATEGORY

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Navigation exercise

NATURE OF ACCIDENT:

Port engine cut out and a/c would not hold altitude on stbd engine necessitating a forced landing with wheels up.

TECHNICAL OFFICER'S REPORT:

Rocker standard broken on No.5 cylinder of the Port engine.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

~~54. Engine failure in air.~~

17. Forced Landing 17

SECONDARY OR CONTRIBUTORY FACTORS:

~~34. Wheels up landing.~~

26. Engine trouble - accident

ACTION TAKEN:

Nil

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 685-L 20

C. C. LTD. 7084-43