CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 11774

Title: Avro Anson Mk. V serial:11774 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-November-20. Anson V s/n 11774. This accident involved 4 people. Flemington F, Mounsey E, Payne JW, Pearson EM

Keywords: RCAFAnson V,11774,8 AOS,8 Air Observer School,Aerodrome,1943-November-20,Flemington,Mounsey,Payne,PearsonRCAF L20

Created: 1943-11-20

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11774

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
8 A.O.S. Ancienne Lorrette	3	M.A.	20-11-43	1630

H.Q. FILE 1100-117-74

A/C TYPE	No.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON V	11774	"B"		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Payne, J.W.	SGT	R161792	P	Uninj.
Flemington, F. GB	LAC	1567795	NAV	Uninj.
Lounsey, E. GB	LAC	1672764	NAV	Uninj.
Pearson, E.M. GB	LAC	1672962	NAV	Uninj.

SIGNAL

NO.	DATE
A.196	20-11

D 14 (REVISED)

NO.	CHECKED
	✓

#4

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Wasp Jr. An 14B	43/4603/20789 Nil 43/4596/20782 Nil	50	25	294	108	158	147

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE OFF
FLIGHT
STAT'RY

INJURY
FATAL
INJ.
3RD
S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Routine navigation flight.

NATURE OF ACCIDENT:

Port power brake locked just after landing causing a/c to ground loop off runway. A/C sled sideway on wet grass until it hit a gravel filled drainage ditch which sheared off the a/c. Stbd wing struck ground first breaking wing spars.

TECHNICAL OFFICER'S REPORT:

Port power brake locked in full "ON" position.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

100/C 35

CLASSIFICATION:

~~46. Brake failure.~~ 7

7. Other

SECONDARY OR CONTRIBUTORY FACTORS:

~~38. Ground loop.~~

~~44. Bad surface.~~

36 Brake Failure 36

ACTION TAKEN:

Nil

R. C. A. F.-L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43