CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 6221

Title: Avro Anson Mk. I serial:6221 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-February-11. Anson I s/n 6221. This accident involved 5 people. Andrews AE, Brackenbury CE, Mcdonald AS, Morrison DJ, Uden LW

Keywords: RCAFAnson I,6221,7 AOS,7 Air Observer School,Aerodrome,1944-February-11,Andrews, Brackenbury,Mcdonald,Morrison,UdenRCAF L20

Created: 1944-02-11

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6221

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
7 A.O.S. Portage la Prairie	2	M.A.	11-2-44	2310

H.Q. FILE 1100-62-21

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON I	6221	"D"		x		x

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
MORRISON, D.J.	SGT	R137837	P	Uninj.
BRACKENBURY, C.E.	LAC	R60403	NAV	Uninj.
ANDREWS, A.E. NZ	P/O	1946	NAV	Uninj.
UDEN, L.W. NZ	LAC	425442	BA	Uninj.
MCDONALD, A.S.	ACI	R167029	WOP	Uninj.

SIGNAL

NO.	DATE
No sig	

D 14 (REVISED)

NO.	CHECKED
2	

CR 5 V 5 T

#12

ENGINE	ENGINE NUMBER (S)
Cheetah IX	A112842/AS13381 Nil
	10324/AS30198 Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE SOLO	ON TYPE DUAL	TOTAL SOLO	TOTAL DUAL
43	192	667	96	697	136

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT: FORCED LANDING, TAXYING, LANDING, TAKE-OFF, FLIGHT, STAT'RY

INJURY: FATAL, INJ., 3RD, S, RAF, NZ

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Navigation exercise night.

NATURE OF ACCIDENT:

Wheels up landing.

CLASSIFICATION:

~~33. Technical defect.~~

17. Forced Landing

SECONDARY OR CONTRIBUTORY FACTORS:

32. U/c defect 35

TECHNICAL OFFICER'S REPORT:

NIL LOC UM/AMC

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

Port venturi tube had been removed for repairs. Proper care not taken on re-installing tubing to see that enough clearance left for u/c when retracted, resulting in U/C coming in contact with tubing and pushing same on to u/c retracting chain and fouling retracting gear.

ACTION TAKEN:

Mechanic severely reprimanded

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43