CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 11462

Title: Avro Anson Mk. II serial:11462 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-August-09. Anson II s/n 11462. This accident involved 1 person. Fletcher V

Keywords: RCAFAnson II,11462,17 SFTS,17 Service Flying Training School,Findlay Manitoba,1944-August-09,FletcherRCAF L20

Created: 1944-08-09

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11462

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
17 S.F.T.S. Souris, Man.	2	South of Findlay, Man.	9-8-44	1145

H.Q. FILE

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON II	11462	"E"1		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Fletcher, V. GB	LAC	1584415	PP	Uninj.

SIGNAL

NO.	DATE

D 14 (REVISED)

NO.	CHECKED
	✓

#25

ENGINE	ENGINE NUMBER (S)
Jacobs L6MB	P.26278/P15373 Nil S.S10982/S25684 Nil.

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE DUAL	ON TYPE SOLO	TOTAL DUAL	TOTAL SOLO
22	26	75	54	117	87

TYPE OF A/C · TYPE OF UNIT · CATEGORY · COMMAND · MONTH · STAGE OF FLIGHT · FORCED LANDING · TAXYING · LANDING · TAKE-OFF · FLIGHT · STAT'RY · INJURY · FATAL · INJ. · 3RD · S · RAF · M · N

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Practicing Forced Landing approaches.

TECHNICAL OFFICER'S REPORT:

Engine Failure.

ILFM/AOP/ES/PM/NK/IL

NATURE OF ACCIDENT:

While practicing forced landing appr- each u/t pilot opened up throttles at app. 200 ft. Engines failed due to air lock. Pilot landed in field.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

17. Forced landing.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine trouble - accident.

ACTION TAKEN:

Nil.

R. C. A. F. L 20 (REVISED)
2M-5-44 (4638) K. P. 8689
H. Q. 885-L 20

C. C. LTD. 20157-44