CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 11517

Title: Avro Anson Mk. II serial:11517 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1945-February-08. Anson II s/n 11517. This accident involved 1 person. Williams S

Keywords: RCAFAnson II,11517,17 SFTS,17 Service Flying Training School,Grande Clairiere Manitoba,1945-February-08,WilliamsRCAF L20

Created: 1945-02-08

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11517

ACCIDENT CLASSIFICATION

27 S.F.T.S. Souris, Man.	COM. 2	PLACE 3 mls. N.E. Grande Clairiere, Man.	DATE 8-2-45	TIME 17.45			
			H.Q. FILE 1100-115-17				
A/C TYPE ANSON II	NO. 11517	CRASH CAT. "D"	S.E.	M.E. x	DAY x	NIGHT	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
WILLIAMS, S., GB	LAC	1568277	P.P.	Uninj.

SIGNAL: NO. LG A.21 — DATE 9-2

D 14 (REVISED): NO. 1 — CHECKED

12

ENGINE	ENGINE NUMBER (S)
Jacobs L6MB	P26174/10878 Nil S25376/9746 Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE DUAL	ON TYPE SOLO	TOTAL DUAL	TOTAL SOLO
8	10	52	36	103	98

TYPE OF A/C · TYPE OF UNIT · CATEGORY · COMMAND · MONTH · STAGE OF FLIGHT · FORCED LANDING · TAXYING · LANDING · TAKE-OFF · FLIGHT · STAT'RY · FATAL INJ. · 3RD · S · RAF

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Practicing Forced Landing Seq.

TECHNICAL OFFICER'S REPORT:

Nil ILFM/R/AOP/PCDE/ES/PM/M/IL/WIE

NATURE OF ACCIDENT:

Pupil practicing forced landings had both motors fail on opening throttles on completion of approach. Occurred on applying power to climb away.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

17. Forced Landing

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine Trouble - Accident.

Carburettor Icing.

ACTION TAKEN: Logged "Carelessness" Extra Duties. for not using carburettor heat.

R. C. A. F. L 20 (REVISED)
2M-5-44 (4638) K. F. 8689
H. Q. 885-L 20

C. C. LTD. 20157-44