CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 6184

Title: Avro Anson Mk. I serial:6184 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 2 aircraft on 1941-December-21. They are: Anson s/n 6092, Anson s/n 6184. This accident involved 2 people. Dame JM, Mcdonald WH

Keywords: RCAFAnson ,6184,3 AOS,3 Air Observer School,Regina Airport,1941-December-21,Dame,McdonaldRCAF L20

Created: 1941-12-21

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6184

CAUSES OF ACCIDENTS

PILOT | OTHERS | AIRFRAME FAILURE | ENGINE FAILURE

32 JU. 31 TECH. 30 DISOB. 29 NEG'NCE 28 INEXP'NCE 27 MISCEL. 26 INSTRUCT. 25 FLT. CONTR. 24 OTHERS 23 PRIMARY 22 FL. CONTS. 21 MOV. SURFS. 20 STAB. SURFS. 19 W. STRUTS 18 LAND. GEAR 17 FLOATS 16 FUSE. OR HULL 15 TAIL SKID OR W. 14 ENGINE MOUNT. 13 MISCEL. 12 UND'TD 11 PRIMARY 10 FUEL SYS. 9 COOL. SYS. 8 IGNIT. SYS. 7 LUB'N SYS. 6 ENG. STR. 5 AIRSCREW A. 4 ENG. CONTS. 3 MISCEL. 2 UND'TD 1 PRIMARY

MISCELLANEOUS CAUSES: HAND O. | INSTS. | WEATHER | DRKNS. | A/C SURF. | OTHER | UND'TD | PRIMARY

STAGE OF FLIGHT: TAXYING | LANDING | TAKE-OFF | FLIGHT | STAT'RY

INJURY: FATAL | INJ. | 3RD. | S.S.

TYPE OF A/C | TYPE OF ENGINE | CATEGORY

UNIT	COM.	PLACE	DATE	TIME
#3 A.O.S. Regina, Sask.	#4	Regina Airport	21-12-41 H.Q. FILE	1140

A/C TYPE	No.	CRASH CAT.	SE	ME	DAY	NIGHT
Anson	6092	C / "C10"		X	X	
Anson	6184					

NAME	RANK	No.	DUTY	INJURIES	SERIOUS: FATAL	SERIOUS: INJURY
Dame, J.M.	Civ.			Uninjured		
McDonald, W.H.	LAC	R110208	Nav	Uninjured		

CARD SERIAL No.

TYPE A/F & ENGINE	No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE	HOURS FLOWN BY PILOTS: INST.	NIGHT	ON TYPE: DUAL	ON TYPE: SOLO	TOTAL: DUAL	TOTAL: SOLO	LAST 6 MOS.
Anson	6092	Slight										
Anson	6184	Slight				Nil	24			580		
Cheetah	11211	Nil ---6092										
Cheetah	11210	Nil ---6092										

SIGNAL No. & DATE	UNIT No. & DATE	COM. No. & DATE	REPORT	FILE	DATE
A36 21-12-41					

NATURE OF ACCIDENT

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 R.A.F. 32

DUTY ON WHICH ENGAGED:

Navigation exercises.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

While taxying on icy surface Anson 6184 collided with Anson 6092, damaging the wings of both aircraft.

PRIMARY CAUSE:

Combination strong wind and icy sloping taxi strip.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Anson 6184 and Anson 6092 collided.

COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:

DATE: MUAT

COMPOSITION: TCH/XGL

MH/RM

RECOMMENDATIONS:

ACTION TAKEN:
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

The sloping section of taxi strip will be covered with sand when slippery.

RECORDED BY DATE

CHECKED BY DATE