

CASPIR Aircraft Accident Cards

Title: Stranraer serial: - Crash Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1941-December-13. Stranraer s/n . This accident involved 5 people. Dunn EI, Lyon HG, Robertson SR, Smith AD, Toole FA

Keywords: RCAFStranraer ,,13 Sqn,13 OT Squadron,Patricia Bay British Columbia,1941-December-13,Dunn,Lyon,Robertson,Smith,TooleRCAF L20

Created: 1941-12-13

TYPE OF ACCIDENT		TYPE OF ENGINE		CATEGORY		TYPE OF ENGINE		TYPE OF ACCIDENT	
PILOT		OTHERS		AIRFRAME FAILURE		ENGINE FAILURE		CAUSES OF ACCIDENTS	
UNIT 13 O.T. Sqn.		COM.		PLACE		DATE 13-12-41		TIME	
Patricia Bay, B.C. W.A.C.		Patricia Bay, B.C.		H.Q. FILE					
A/C TYPE		No.		CRASH CAT.		SE		ME	
Stranraer				nqn				X	
NAME		RANK		No.		DUTY		INJURIES	
Lyon, H.G.		P/O		J5698		P		Uninjured	
Smith, A.D.		P/O		J7750		Pass.		Uninjured	
Toole, F.A.		CPL.		R53246		2/P		Uninjured	
Robertson, S.R.		LAC		R61898		OC		Uninjured	
Dunn, E.I.		AC1		R91690		OC		Uninjured	
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.	
Stranraer									
DATE		UNIT No & DATE		COM. No & DATE		REPORT		FILE	
SIGNAL No & DATE		UNIT No & DATE		COM. No & DATE		REPORT		FILE	
NATURE OF ACCIDENT		NATURE OF ACCIDENT		NATURE OF ACCIDENT		NATURE OF ACCIDENT		NATURE OF ACCIDENT	

COURT OF INQUIRY, INVESTIGATING OFFICER

Operational night flight.

DATE:

COMPOSITION:

While executing night landing the port wing tip float struck stern of crash boat.

RECOMMENDATIONS:

Inexperience of pilot in night flying
and crash boat was out of position.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Aircraft struck stern of crash boat while landing.

RECORDED BY

DATE _____

CHECKED BY

DATE _____